

FOTO SURVEY KONDISI JALAN TAHUN 2022

Ruas Jalan : Jl. Jemb. Ulin RT.9 Ds. Liang Ulu



Lokasi : 0+000
Kondisi : Sedang
Lebar : 2
Tipe Perkerasan : Aspal



Lokasi : 0+100
Kondisi : Sedang
Lebar : 2
Tipe Perkerasan : Aspal

No. Ruas	Nama Ruas	DPU Kab. Kutai Kartanegara	Petugas Survey	Halaman
551	Jl. Jemb. Ulin RT.9 Ds. Liang Ulu		Damar & Wawan	1