

FOTO SURVEY KONDISI JALAN TAHUN 2022

Ruas Jalan : Gg. Langgar/13 RT.6 Kel. Timbau



Lokasi : 0+000
Kondisi : Rusak Ringan
Lebar : 3
Tipe Perkerasan : Beton



Lokasi : 0+100
Kondisi : Rusak Ringan
Lebar : 3
Tipe Perkerasan : Beton

No. Ruas	Nama Ruas	DPU Kab. Kutai Kartanegara	Petugas Survey	Halaman
636	Gg. Langgar/13 RT.6 Kel. Timbau		Dimas & Rija	1

FOTO SURVEY KONDISI JALAN TAHUN 2022

Ruas Jalan : Gg. Langgar/13 RT.6 Kel. Timbau



Lokasi : 0+200
Kondisi : Rusak Berat
Lebar : 3
Tipe Perkerasan : Beton



Lokasi : 0+210
Kondisi : Rusak Berat
Lebar : 3
Tipe Perkerasan : Beton

No. Ruas	Nama Ruas	DPU Kab. Kutai Kartanegara	Petugas Survey	Halaman
636	Gg. Langgar/13 RT.6 Kel. Timbau		Dimas & Rija	2

